




# Paul Anwiler Tech Services


Guitar Amplifier Repairs - Upgrades - Modifications  
419.349.2207 <PaulAnwiler@aol.com>




## Photos of Fender® amps with transformer and capacitor upgrades




Mercury Magnetics® transformers in Fender® SuperSonic. Note: extra wire is service loop for power supply board.




A wide view of the Fender® SuperSonic illustrates the high component density of all the circuit boards.




Mercury® power transformer with tube rectifier mod in Fender® Custom Vibrolux Reverb. No service loop needed.



A close-up shows the cap installed on end due to a lack of room. NOTE: heat shrink tubing & RTV silicone.



Cap upgrade in Fender® Super Reverb (Orange Drop - 716P Polypropylene Film caps with copper leads).



An additional view of the Fender® SuperSonic shows the Mallory® type 150M Series - metalized polyester film caps.